

R.H.I.P

RAIL HEALTH INSPECTION PROGRAM

PROGRAM DELIVERABLES

- **ASSET LIST — ITEMIZED LIST OF THE EQUIPMENT INSPECTED**
- **DEFICIENCY SUMMARY — HIGHLIGHTS ALL PROBLEM AREAS**
- **RAIL HEALTH INSPECTION REPORTS — DETAILED FINDINGS OF THE INSPECTION**
- **QUOTES — ITEMIZED PRICE ESTIMATE (WITH PHOTOS) FOR RECOMMENDED REPAIRS**
- **COMPLIANCE TO FRA SAFETY ADVISORY 99-1**
- **PROFESSIONAL CONSULTATIVE SERVICES**

BECAUSE SAFETY AND RELIABILITY MATTER...

The safety and reliability of your equipment matters. Therefore, R.H.I.P. is the solution for you. Information is available in electronic or print versions and uses simple color-coded identifiers which make it easy to review and analyze. Our program also allows for customization of services to meet unique production needs.

THE PROCESS


The process starts with a consultation between your team and Whiting Services' Technical Sales to develop the appropriate inspection schedule. This may involve Periodic Inspections, Frequent Inspections or Preventative Maintenance Visits.

Once the inspection(s) are complete, the findings are documented via a R.H.I.P. Report. A review meeting is conducted to go through the report and ensure you have a thorough and clear understanding of the health of your equipment along with our recommended action(s).

Deficiency Summary

of Deficiencies

- High - 1
- Medium - 9
- Low - 3
- Good - 110



Deficiencies by Asset

Customer ID# - TagID	WSI - Identifier	High	Med	Low	# Forms
Jack #1	D966	1	2	1	1
Jack #2	10799	0	3	1	1
Jack #3	10797	0	2	1	1
Jack #4	10796	0	2	0	1
Jack #5	10798	0	0	0	1
Overall:		1	9	3	5

Deficiency Explanations

High = Significant probability to cause equipment failure or create a safety hazard. Deficiency needs to be addressed prior to returning equipment to service.

Medium = Potential to cause equipment failure or create a safety hazard

Whiting Drop Table

Drop Table Inspection

Completed by: WSI

Location: Monee, IL

Area: 12301 s Indiana

Customer: D966

Location:

Status: In Service

Drop Table Manufacturer: Whiting

Drop Table Serial Number: D966

Drop Table Capacity: 70

Service Top Mfg.: Whiting

	Description of Repairs	Price	Repair Date
Drop Table Inspection Report			
	(F) Fail - Centering limit switch and sealrite is damaged 3" 1/2" sealrite 2 90 fittings		
	Pass, Fail - NW .084 SW .126 SE .083 NE .120		

Asset List

Drop Table Inspection

id	Drop Table Manufacturer	Drop Table Serial Number	Drop Table Capacity	Service Top Mfg.	Comments
D966	Whiting	D966	70	Whiting	

Portable Jack Inspection

id	Jack Serial Number	Jack Capacity	Jack Manufacturer
10796	MAL2378	35 Tons	Whiting
10797	MAL2377	35 Tons	Whiting
10798	MAL2376	35 Tons	Whiting
10799	MAL2375	35 Tons	Whiting

THE RESULTS

The comprehensive R.H.I.P Program paired with our world-class service help improve safety and productivity while lowering the total cost of ownership.

Whiting Services, Inc - there for you when you need a lift.



@WHITINGCORP



FACEBOOK.COM/WHITINGCORPORATION

PHONE: (800) 336-7900

FAX: (708) 587-2231

WWW.WHITINGSERVICES.COM

INQUIRIES@WHITINGSERVICES.COM